

## **SAFE WORK PRACTICES AND RESTRICTED LICENCE TOOLS TO BE SUPPLIED BY PARTICIPANTS**

### **Applicants – what applicants need to bring**

#### **Personal Protective Equipment (PPE)**

To meet OH&S (occupational health and safety) requirements, you must bring basic PPE for your practical skill assessment in your trade.

Essential:

- Eye protection (goggles, glasses)
- Foot protection (safety boots)
- Insulated gloves rated to 650V (marked with relevant Australian Standard AS2225)
- Flame resistant outers for mechanical protection
- Skin/body protection – protective clothing (long sleeve cotton overalls)



Note: Basic PPE is mandatory and must be worn at all times while the practical skills assessment is being conducted.

Optional:

- Hair and beard wear/protection (hair mesh)
- Hearing protection (ear plugs, ear muffs)

## Equipment to be supplied by participant:

- Insulated gloves rated to 650V (marked with relevant Australian Standard AS2225)
- Flame-resistant outer gloves for mechanical protection (both sets of gloves are required for training and assessment)
- 500V DC insulation resistance tester and test leads (analogue indicating face meter)
- Multimeter and test leads – Cat 3 (CAT III-1000V) or Cat 4 (CAT IV-600V)
- 2 x out of service with ties
- 2 x danger tags with ties
- 2 x safety padlocks
- Circuit breaker lock dog
- Screwdrivers and pliers
- Side-cutters
- Hand tools
- Electrical grade insulation tape
- Black wire ties

